



Square nested and g-code created in sheetcam. Simulator runs correctly.



Loads and previews like this on the plasma



Part previously cut correctly with a file saved on the CNC hard drive



How the part displays now after the gearbox change when I want to re-cut the file.